


Sensor Type: I-SCAN10 × 10



Exploded View

		General Dimensions			Sensing Region Dimensions							Summary		
Type	Map	Overall Length <i>L</i>	Overall Width <i>W</i>	Tab Length <i>A</i>	Matrix Width <i>MW</i>	Matrix Height <i>MH</i>	Columns			Rows		No. of Sensels	Sensel Density	
		(mm)	(mm)	(mm)	(mm)	(mm)	<i>CW</i>	<i>CS</i>	<i>Qty.</i>	<i>RW</i>	<i>RS</i>	<i>Qty.</i>	(sensel per sq-cm)	
I-SCAN	5800	252	27.8	113	13	13	0.52	1.27	10	0.52	1.27	10	100	59.2

Application Examples: Small Contact Patches.